

3. Machine specifications

3.2.2 PUMA 400LM




Fig. 3-2 Dimensional drawings